

# Driver Release Note

Product: FL1000 Series

Driver Version (Windows): 3.0.116.3

Release Date: 2011/03/02

## Revision History

Version	Issue Date	Comment
3.0.116.3	2011/03/02	Fix the device lost issue after reboot with some system. Enhance the performance Fix CHT8000 smart phone issue Fix i-phone issue Fix C120 issue Fix USB3.0 Hub disable/enable issue.
3.0.114.13	2011/01/26	Fix Asus Audio issue. Fix Razor Mouse from PIL. Fix Creative Zen PIL device Fix Logitech MOMO (PIL Device) Enable Performance Hack for 4-Processor machines Enable P2 override to save power Add support for special devices like TV Tuner
3.0.110.12	2010/11/27	Include the AP to show the message when plug USB3.0 device into the USB2.0 port. Enhance the hub compatibility Fix SiBEAM issue To enhance the bad cable compatibility
3.0.108.16	2010/11/01	Fix Cannon Printer issue. Support devices with no endpoints. Always check all hub ports for connected devices when hub driver starts.
3.0.105.11	2010/10/01	Enhance some device for suspend/resume behavior Fix issue when TRB has length > 64K Full support for USBLyzer Allow U1/U2 code to be turn on/off

		Enhance USB3.0 hub interoperability Make resume faster with/without hub Resume time much faster when device removed during suspend
3.0.100.58	2010/09/01	Root Hub support Fix TV Tuner issue Enhance FL1009 suspend/resume Fix WLK issue Isoch changes for high bandwidth devices Enhance USB3.0 device and hub Fix 3G dongle issue
3.0.99.53	2010/08/06	Fix IPOD Shuffle issue. Add support for PORT_RESET for devices attached to hubs. Merge FL1009 Code Includes xHCI version 1.0 support Hub Driver Rename Add legacy usb support for BIOS company Fix OCZ drive Synchronize RESET and STALL handling. Add support for User Mode notification. Remove need for "Vendor"=1 for WLK Fix Apple Keyboard INF issue USB3 Port Power Save Add Root Port Number to Serial Number Ipod Touch fix Fix 3G dongle due to serial number too long issue Fix FL1009B suspend/resume on two ports issue Turn off Run-Stop bit when driver disables Put in work around for Afatech (TVTUNER)
3.0.98.11	2010/07/01	WLK1.5 support (WHQL certified) Fix the issue of USBView with Hub info Fix the issue of re-plug under hub when S3/S4 Fix the compatibility issue of Logitech Camera, Keyboard, Billionton docking, MX6000 webcam, ECZ card reader Fix incorrect size of IRP return (TV tuner issue)
3.0.96.4	2010/05/26	Enhance USB3.0 compatibility

3.0.93.14	2010/05/06	<p>WLK1.5 support (WHQL certified)</p> <p>Fix bugs:</p> <p>Device lost after express card unplug/plug with device connected</p> <p>Support Keijet USB to VGA adaptor</p> <p>It's beta version without WHQL certified (need press F8 when using 64bit OS)</p> <p>Fix bugs:</p> <p>File transfer fail by using pen drive through express card</p>
3.0.89.14	2010/04/19	<p>WLK1.5 support (WHQL certified)</p> <p>Fix bugs:</p> <p>printer unplug hang</p> <p>verifier crash and blue screen</p> <p>Enhance the warm reboot stability of Cyberslim device</p> <p>Add support for devices that use scatter/gather lists for control endpoints.</p>

## **Driver Package**

This driver is official released with WHQL.

There are two drivers in one package:

32bit.msi: for 32bit OS of Windows 7/Vista/XP

64bit.msi: for 64bit OS of Windows 7/Vista/XP

## **Driver Upgrade**

If you install previous version by using inf, please use device manager to uninstall previous version. Please remember to link one USB2.0 hub to uninstall the hub driver.

If you install previous version by using the install shell, please use control table to uninstall the previous version.

After you uninstall the previous version, you could upgrade the driver.